

CONFIDENTIAL

12 July 1954

MEMORANDUM FOR: Chief, Maintenance

SUBJECT: Construction for Branch VIII

REFERENCE: Our Verbal Conversation, 12 July 1954

25X1A6a

1. Branch VIII is urgently in need of construction and repair work to maintain its facilities here at [REDACTED] This will consist of the following:

a. One Quonset hut 20' x 50' to be erected along the northwest end of the present boat house at [REDACTED]. This is to fit right on to the end of the boat house, flush with the drive side and running back towards the river. This will give a unit shaped as an "L".

b. One double door approximately 12' wide is needed on the ^{SW} side of the Quonset hut with the edge of the door 20' from the river end of the hut.

c. A foundation and concrete floor will be needed under the Quonset hut.

d. Electricity and water will have to be hooked up to the building with an inside ^{case} arrangement and an outside connection for a hose on the east side.

e. The floor should be laid with a floor drain so the floor can be washed down and dried.

f. Windows should be built in both ends of the Quonset hut (river end and drive end).

g. One water cooler (drinking fountain) should be installed.

25X1A6a

NOB NO. 54-96337A BOX NO. 1 FLD NO. 11 DOC. NO. 1 NO CHANGE
IN CLASS/ DECLASS/ CLASS CHANGED TO: TS & RET. JUST. 22
NEXT REV DATE 89 REV DATE 9779 REVIEWER 8293 TYPE DOC. 02
NO. PGS. 2 CREATION DATE 09/11/03 CLASS S
REV CLASS C REV COORD. AUTH: HR 70-3

THE UNIVERSITY OF CHICAGO

CONFIDENTIAL

CONFIDENTIAL

i. A door (standard house door) will have to be cut in the Quonset hut end of the frame boat house, to provide entrance from one to the other.

j. The ground area will need additional gravel, both on the drive and in the slipway.

k. The slipway will need repair.

l. The Dock will need repair.

25X1A6a

m. The  anchorage will need enlarging on the side opposite the Dock.

2. This work is urgently needed so that Branch VIII can continue operations. It will have to be completed by 1 September; however, if it can be finished sooner, it would help tremendously.

25X1A9a 

~~SECRET~~
CONFIDENTIAL